



Case Study

Customer: Food City Grocery Store – Deli
Knoxville, TN



Category: Commercial

Application: Deli – Double Cook Steamer

The Challenge: Problem with scaling on the top and bottom steamer ovens. The bottom oven also had very low water pressure coming into the oven.

The Solution: A 3/8" Scaleton was installed on the water line connected to the steamer ovens.

Results: After having the unit installed for just 5 days there was no scale buildup in either of the ovens and the lower oven's water pressure had increased.

